





POWER STRIP INSTRUCTIONS

- 1. Mount power strip on mounting screws inside the cabinet at the location shown to the left.
- 2. Cord may exit through provided grommet hole in the bottom/rear of cabinet, or you may provide your own means of providing power.

This drawing is the property of Collins Manufacturing Company and is protected under copyright law.

collins

Collins Manufacturing 2000 Bowser Rd. Cookeville TN 38506

Title: QSEp Styling Station w/ Mirror Frame & Ledge

Size: #: **405-48** Drawn By:

Date: Sheet #: **2**

Quantity -

Finish Schedule

Face Color -

Top Color -

Toe Color -

Pulls -

Interior -

Other (Specify) -

Installation Notes:

- 1. All hardware needed for assembly is included.
- 2. Large items are preassembled at the factory to ensure proper alignment. Items are then disassembled into managable sections for shipping purposes and ease of reassembly.
- 3. Shipping cleats need to be removed before installation. These cleats are installed to prevent damage.